SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-FLP-545

2-FLP-545 · ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 -Clipper - leather seats · 28 October 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FLP-545
Manufacturer	FORD
Model	Focus
Model Versions	ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 - Clipper - leather seats
Body Type	5 door hatchback
Color	Black
Paint Type	Metallic
Production Year	2024
KW	114

Fuel Type	Hybrid Gasoline
VIN	WF0PXXGCHPRG15231
Cylinder Capacity	999 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	11-06-2024
Odometer	67.037 Km
Numer Of Keys	1
Interior	Black
Number Headrests	5

Images
































Accessories

- ABS
- Airbags
- Alloy wheels
- Audio System
- Automatic air conditioning
- Bluetooth car kit
- Central door locking
- Centre armrest
- Cruise control
- Electric rear windows
- Electric windows front

- Electrically adjustable driver\\\\'s seat
- Electrically adjustable exterior mirrors
- Front & rear parking sensors
- Leather steering wheel
- Navigation system
- Rear view camera
- Roller cover / parcel shelf
- Seat heating
- Steering wheel multifunction
- Steeringwheel – Heated
- Windscreen – Heated

Condition

Condition exterior	Adequate
Condition interior	Adequate
Last Maintenance	Unknown
Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Rear Left	5 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Front Right	3 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Rear Right	5 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Spare Tire Type	Compressor					

Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Reservesleutel	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small scratch(es)	Polish	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Dent(s)	Stijl	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Small scratch(es)	Touch-up / Polish	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Small dent(s)	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Dent(s)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Small scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Small scratch(es)	Polish	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Dent(s)	Panelbeating & Spray	No