



OPEL COMBO LIFE: 3379-LZV

Vinnumber:	W0VECYHT2NJ668279	Versionname:	1.5 TD 75kW (100CV) S/S Edition Plus XL monovolumen 75kW 5P manual
First Registrationdate:	19/08/2022	Fiscalpower:	
Expertise Mileage:	150371	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	1	Central consol F
Number keys remote:	1	Luggage cover
Windows electric F:		Front parking sensors
Cruise Control:		Rear parking sensors
Steering wheel multifunctional:		
Radio multimedia:		
Type of climate control:	Manual climate control	

Tyres

205/60/16/92 H				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/60 R 16 92 H
Tyre size FR				205/60 R 16 92 H
Tyre size RL				205/60 R 16 92 H
Tyre size RR				205/60 R 16 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit:	Yes
-------------	------------

Registration document, Missing, Repair/replace (lump sum)




Ignition key, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Boot lid covering R, Scratch(es), Replace



Boot lid covering R, Scratch(es), Replace



Boot lid covering R, Scratch(es), Replace



Wing RL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Outside rear-view mirror housing L, Scratch(es), Paint



Wheel cover FL, Scratch(es), Replace



Bumper F, Scratch(es), Paint





Wheel cover FR, Scratch(es), Replace



Wing FR, Scratch(es), Paint



Door FR, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering

