

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia					
				Policyholder			Opposite party				Opposite party company				
				Operation 2026	Claim number			Code / Agency				Date accident 25/06/2026			
				Expert code		Adjuster code		Policy number			Injured person can recover the VAT				
Date assignment 25/06/2026		Date first survey 06/07/2026		Place Rovigo		C/O VAR	Repairs TO START		Photo	Lien in favor of		Expiry date			
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)												Formerly plate			
Lessee / Co-owner												Date of overhaul			
Vehicle (Brand - Model - Version) PEUGEOT 2008 BlueHDi 130 EAT8 Allure Pack S/S							Plate GN577LL		Vin Chassis VR3UDYHZSPJ552064			First Registration 27/03/2023			
Usage status NON CONOSCIUTO		Km 152065	Tyres % 50	Color Azzurro		Type of enamel METALLIZED/DOUBLE			Consistency of damage YES		Type of Expert's report DEFINITIVE				
Equipment															
Approval code		For commercial vehicles	Carrying Qls 0	Tare, Q 0	Wheelbase	Seats No. 0	Axles 0								
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses									
Damaged items / restoration operations						SR		LA		VE		ME	D.M. S.C.	Costs of spare parts * (VAT excluded)	
						Dif	Time	Dif	Time	Dif	Time	Time			
1	9844989280	Windshield				S		S		S					
1	Codice Ricambio	Kit sigillante				S		S		S					
1	98385167XT	Rear central bumper				S		S		S					
1	1638159380	Serie guarnizioni coperchio punterie				S		S		S					
1	9812647280	Sede albero a camme				S		S		S					
1	9826028980	Catena distribuzione sup.				S		S		S					
1	9823954880	Pistoncino tendicatena sup.				S		S		S					
1	1638159680	Kit cinghia distribuzione				S		S		S					
1	9825013780	Albero a camme aspirazione				S		S		S					
1	9825017880	Albero a camme scarico				S		S		S					
8	1692287080	Bilanciere valvola scarico				S		S		S					
8	Codice Ricambio	Bilanciere valvola aspirazione				S		S		S					
1	1680682480	Filtro olio				S		S		S					
1	Codice Ricambio	Olio Motore lt5,5				S		S		S					
1	983851711T	Front bumper				M		M		M					
1	983855131T	Rear side bumper		L		L		L		L					
1	983855121T	Rear side bumper		R		L		L		L					
1	9831048080	Rear door		R		L		L		L					
1	Codice Ricambio	Rigenerazione cerchio lega post.				R									
1	Codice Ricambio	Igienizzazione interni													

New for old value (N)		Remarks	
		Pneum. Pirelli 215/6 R17. Vhl sporco. Alert Anomalia cambio far riparare. Motore non avviabile e disp. int. non funzionanti; computo integrato con preventivo fornitoci	

ALPHABET

Telaio VR3UDYHZSPJ552064

GN577LL

PEUGEOT 2008 BlueHDi 130 EAT8 Allure Pack S/S aut. sports utility vehicle 130CV 5P automatico

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
26.391	24/11/23	Tagliando a 30 000 km	Tagliando a 30 000 km
62.490	26/07/24	Tagliando a 60 000 km	Tagliando a 60 000 km
92.000	27/01/25	Maintenance	Generico
92.000	27/01/25	Tagliando a 90 000 km	Tagliando a 90 000 km
128.500	10/11/25	Tagliando a 120 000 km	Tagliando a 120 000 km