



Vehicle History Report

2016 PORSCHE CAYENNE

Vehicle reference:

WP1ZZZ92ZGLA69548

Body type:

Estate

Gearbox type:

Automatic

Engine size:

4134 cm³

Fuel type:

Diesel

Combustion engine power:

283 kW / 385 hp

Drive:

AWD

Quick check



Damage

No damage reported to CARFAX



Import

Vehicle imported

Legend



No issues reported or indicated



Valuable Information



Requires attention



Data unavailable

Extra information

French history check BETA

Check if this vehicle has any history in France. You need to be the owner of this vehicle or be authorized by its owner to perform the check. Additional French history reports are provided in French and are available free of charge for all vehicles ever registered in France.

Check
online
version

Damage overview

✓ No issues reported

Our data shows **no damage or accident records** for this vehicle.

Keep in mind

CARFAX only reflects information that's been reported to us.

While having no reported damage is a positive sign, it's still important to take a close look at the vehicle during your test-drive:

- Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.
- Don't hesitate to ask the seller for additional details or service documentation.



Recommended maintenance

Default schedule

Provided by CARFAX Europe



Vehicle age

10 years, 1 month

Routine maintenance is essential for preserving a vehicle's reliability.

Critical past due service tasks

These service tasks are expected based on the vehicle age. Verify if they were completed.

Before buying, ask the seller:

- Are service records available?
- Were the following services performed?

 **Engine oil and oil filter** **due 10 times**
Change every year

 **Brake fluid** **due 5 times**
Change every 2 years

 **Diesel fuel filter** **due 5 times**
Change every 2 years

Costly upcoming service tasks

Before buying, confirm whether:

- Any of the upcoming maintenance tasks are already completed.
- You've accounted for related costs in your future budget.

 **Brake discs and pads**
Inspect yearly, replace as needed


 **Tires**
Inspect yearly, replace as needed

CARFAX tips




Keeping up with scheduled servicing is a strong indicator that the vehicle has been well cared for and is in good overall condition.

Mileage Check



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.



Owner(s) abroad

Purchase year: **2016**

There is no more information available about owners abroad.



Owner 1 in Italy

Purchase year: **2018**

Length of use: **5 years 4 months**

Type of owner: **Private individual**

Owner 2 in Italy

Purchase year: **2023**

Length of use:	less than a month
Type of owner:	Commercial business
Owner 3 in Italy	
Purchase year:	2023
Length of use:	4 months
Type of owner:	Commercial business
Owner 4 in Italy	
Purchase year:	2023
Type of owner:	Private individual

Technical details

Engine and performance

Fuel type
Diesel

Combustion engine power
283 kW / 385 hp

Environment and consumption

CO2 emissions in mixed driving
319 g/km 

Fuel consumption in mixed driving
14.07 l/100km

Other information

European vehicle category
M1

Number of doors
5

History information

Date	Mileage	Event
2016-06-13		First registration abroad
2018-03-09		Imported to Italy Registered in Italy New owner reported Owner type: private individual
2020-06-05	58 808 km	Inspected in Italy
2022-06-07	101 741 km	Inspected in Italy
2023-07-11		New owner reported Owner type: commercial
2023-07-18		New owner reported Owner type: commercial
2023-12-05		New owner reported Owner type: private individual
2024-06-07	149 442 km	Inspected in Italy Inspection passed Inspection valid until 2026-06-30

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

Carfax glossary

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Model year

This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions](#).