



### Peugeot 2008: N817XP

Vinnnummer:	<b>VR3UKZKXZMJ927693</b>	Versionname:	<b>e-2008 100kW/ 50kWh GT</b>
First Registrationdate:	<b>31/12/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>38452</b>	Power Kw:	<b>100</b>
Bodytype:		Body colour:	<b>Gris Artense metaallak</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>568</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

### Options

Number of keys total	<b>2</b>	Lining semi-leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

### Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 96 / H / Aluminium	6,2 mm	Bridgestone	Winter
	Right	215 / 60 / 17 / 96 / H / Aluminium	5,8 mm	Bridgestone	Winter
Rear	Left	215 / 60 / 17 / 96 / H / Aluminium	6,0 mm	Bridgestone	Winter
	Right	215 / 60 / 17 / 96 / H / Aluminium	5,6 mm	Bridgestone	Winter

### Assistance equipment

Number of charging cables (rapid charge)	<b>1</b>
--	----------

### Door FL, Bad repair, Repair and paint (complete)



### Door RL, Bad repair, Repair and paint (complete)



### Wheel arch cover FL, Scratch(es), Replace



Bumper trim F, Scratch(es), Replace



Bumper F, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Roof, Dent(s), Repair and paint (complete)



<b>Kenteken</b>	N817XP
<b>Merk Model</b>	Peugeot e-2008 100kW/ 50kWh GT
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	31-12-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
24-03-26	36.231	APK
28-05-25	31.005	Vervanging band
16-12-24	27.551	Raammechanisme elektrische ramen