



### Volkswagen ID.4: L325JK

Vinnumber:	<b>WVGZZZE2ZMP004966</b>	Versionname:	<b>ID 4 Outgoing 150kW / 77kWh 1ST Automaat</b>
First Registrationdate:	<b>16/06/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>99837</b>	Power Kw:	<b>150</b>
Bodytype:		Body colour:	<b>Mangan Grey metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>848</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

### Options

Number of keys total	<b>2</b>	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Rear parking sensors
Radio multimedia		Rear view camera

### Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	255 / 45 / 20 / 101 / T / Aluminium	4,3 mm	Hankook	Summer
	Right	255 / 45 / 20 / 101 / T / Aluminium	4,5 mm	Hankook	Summer
Rear	Left	255 / 45 / 20 / 101 / T / Aluminium	4,5 mm	Hankook	Summer
	Right	255 / 45 / 20 / 101 / T / Aluminium	4,0 mm	Hankook	Summer

### Assistance equipment

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>1</b>

### Bonnet, Scratch(es), Repair and paint (complete)



### Bumper F, Scratch(es), Repair and paint (complete)



### Wing RR, Dent(s), Repair and paint (complete)





Door FR, Scratch(es), Repair and paint (complete)



Rear window, Scratch(es), Replace



<b>Kenteken</b>	L325JK
<b>Merk Model</b>	Volkswagen ID 4 Outgoing 150kW / 77kWh 1ST Automaat
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	16-06-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
12-02-26	91.626	Ruitenwischerblad(en) achterzijde
12-02-26	91.626	Ruitenwischerblad(en) voorzijde
15-10-24	64.408	Accu
29-02-24	53.840	Remschijf + blokken voor
29-02-24	53.840	Ruitenwischerblad(en) achterzijde
29-02-24	53.840	Ruitenwischerblad(en) voorzijde