

Inspection data

Inspection date **07/05/2026 12:38**

Vehicle data

License plate

Make / Type **SKODA ENYAQ IV**


VIN **TMBJB7NY5PF007149**

First registration date **03/10/2022**

Mileage **99.574 km**



Vehicle pictures





Tires					
Location	Position	Depth	Dimension	Make	Type
Voor	Links	7,0 mm	235/55 R 19 105 T	Continental	Winter
Voor	Rechts	7,0 mm	235/55 R 19 105 T	Continental	Winter
Achter	Links	6,0 mm	235/55 R 19 105 T	Continental	Winter
Achter	Rechts	6,3 mm	235/55 R 19 105 T	Continental	Winter

Damages with pictures

Claim(s) own risk to be invoiced

Deksel / Klep koffer

Deuk(en) en kras(sen)

L1 - Herstellen en schilderen
(compleet)



Bumper deel A M

Kras(sen)

E - Vervangen



Not invoiced

Bekl bumper A

Kras(sen)

E - Vervangen

