



SKODA SUPERB COMBI

Vinnumber:	TMBJW9NP5M7060382	Versionname:	1.4 TSI iV 160kW DSG6 Clever
First Registrationdate:	16/04/2021	Fiscalpower:	
Expertise Mileage:	137449	Power Kw:	160
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1524
Fueltype:	Hybrid Petrol		
Maintenance:	NOT OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar collapsible
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

215/55/17/92 H				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 92 H
Tyre size FR				215/55 R 17 92 H
Tyre size RL				215/55 R 17 92 H
Tyre size RR				215/55 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Total cost ex VAT	1584,43
Service, Maintenance, Check	0,00



Door panel RR, Scratch(es), Acceptable 0,00



Bonnet, Chemical polution, Polish 0,00



Bumper moulding F, Dent(s), Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Wing RL, Scratch(es), Acceptable 0,00



Step L, Scratch(es), Repair and paint (complete) 161,81



Door FL, Scratch(es), Repair and paint (complete) 534,95



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete) 161,81



Door RL, Dent(s) and scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 355,89



Tailgate / Boot, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), 0,00



Wing FR, Scratch(es), Repair and paint (complete) 369,97



Door FR, Scratch(es), Acceptable 0,00



Door RR, Dent(s) and scratch(es), Acceptable 0,00



Wing RR, Scratch(es), Acceptable 0,00

