MACADAM










Volvo XC40: N236TL

Vinnumber:	**YV1XZEFVKN2721994**	Versionname:	**XC40 Recharge Pure Electric 170kW/70kWh Core automaat**
First Registrationdate:	**30/12/2021**	Fiscalpower:	
Expertise Mileage:	**118620**	Power Kw:	**170**
Bodytype:		Body colour	**Black Stone solid**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**663**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Hook	
Autom climate control		Rear view camera	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 50 / 19 / 103 / H / Aluminium	5,6 mm	Michelin	All season
	Right	235 / 50 / 19 / 103 / H / Aluminium	5,8 mm	Michelin	All season
Rear	Left	235 / 50 / 19 / 103 / W / Aluminium	7,0 mm	Pirelli	All season
	Right	235 / 50 / 19 / 103 / W / Aluminium	7,2 mm	Pirelli	All season

Assistance equipment

Number of charging cables (rapid charge)	**1**

Door FL, Scratch(es), Repair and paint (complete)








Wing FL, Scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)






Wing RL, Scratch(es), Repair and paint (complete)




Bumper trim F, Deformed / Strained, Replace





Bonnet, Scratch(es), Repair and paint (complete)




Fuel cap cover, Scratch(es), Repair and paint (complete)




Door RR, Bad repair, Repair and paint (complete)




Bumper corner RR, Scratch(es), Repair and paint (complete)





Bumper corner RL, Scratch(es), Repair and paint (complete)





Bumper moulding R, Deformed / Strained, Replace and paint




Bumper RM, Scratch(es), Replace




Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)







Roof, Chemical polution, Repair and paint (complete)






Onderhoudshistorie van: YV1XZEFVKN2721994

ALPHABET

Kenteken	N236TL
Merk Model	Volvo XC40 Recharge Pure Electric 170kW/70kWh Core automaat
Brandstofsoort	Elektrisch
Datum deel1	12/30/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
7/13/26	112,694	Onderhoudsbeurt
7/13/26	112,694	Remvloeistof
7/13/26	112,694	Ruitenwisserblad(en) achterzijde
7/13/26	112,694	Ruitenwisserblad(en) voorzijde
12/10/25	98,047	APK
10/14/25	93,988	Parkeersensor
10/14/25	93,988	Vervanging band
3/7/25	83,444	Onderhoudsbeurt
3/7/25	83,444	Uitlijnen voor en achterwielen
3/7/25	83,444	Vervanging band
11/18/24	71,160	Remvloeistof
11/9/23	41,646	Vervanging band