



## CITROËN C4: 4349-MBW

Vinnnumber:	<b>VR7BBYHSANE059748</b>	Versionname:	<b>Citroen BlueHdi 110 S&amp;S Feel Pack berlina con portón 81kW 5P manual</b>
First Registrationdate:	<b>25/10/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>133084</b>	Power Kw:	
Bodytype:	<b>Berline</b>	Body colour:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:			
Fueltype:	<b>Diesel</b>		
Engine functioning:	<b>Yes</b>		
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>No</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>No</b>		

## Options

Number of keys total	<b>1</b>	Central consol F
Number keys remote	<b>1</b>	Luggage cover
GPS big screen color		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	<b>Autom climate control</b>	

## Tyres

195/60/18/96 H				
Summer tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>
Tyre profile depth FL				<b>4.0</b>
Tyre profile depth FR				<b>4.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>195/60 R 18 96 H</b>
Tyre size FR				<b>195/60 R 18 96 H</b>
Tyre size RL				<b>195/60 R 18 96 H</b>
Tyre size RR				<b>195/60 R 18 96 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>259</b>
Tyre make FR				<b>259</b>
Tyre make RL				<b>259</b>
Tyre make RR				<b>259</b>

## Assistance equipment

Repair kit	<b>No</b>
<b>Door panel RR, Scratch(es), Repair/replace (lump sum)</b>	



Door panel FR, Scratch(es), Repair/replace (lump sum)



Boot lid covering R, Scratch(es), Repair/replace (lump sum)



Door panel RL, Scratch(es), Repair/replace (lump sum)



Steering wheel, Worn, Repair/replace (lump sum)



MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Ignition key, Missing, Repair/replace (lump sum)



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



Fender moulding RL, Scratch(es), Repair and paint (complete)



Outer door handle RL, Scratch(es), Paint



Bumper moulding FL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre repair kit, Missing, Repair/replace (lump sum)



Tailgate / Boot, Dent(s), Repair and paint (complete)



Bumper moulding R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Fuel cap cover, Scratch(es), Paint

