



RENAULT TWINGO: FN-828-FA

Vinnumber:	VF1AH000264750559	Versionname:	RENAULT TWINGO Zen SCe 75 (TRANSFO) VF [5P]
First Registrationdate:	23/01/2020	Fiscalpower:	5-75CH-4cv (bi-corps VU)
Expertise Mileage:	201083	Power Kw:	55
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Grey
Fueltype:	Petrol	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Category:	VS		

Options

Number of keys total	1	Radio	
Number keys remote	1	Luggage cover	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Type of climate control	Manual climate control		

Tyres

	165/65/15/81 T			
Summer tyres:	Fr.L.	Other: 45%	Fr.R.	Other: 40%
	Re.L.	Other: 75%	Re.R.	Other: 95%
Tyre profile depth FL				5.4
Tyre profile depth FR				5.5
Tyre profile depth RL				3.5
Tyre profile depth RR				1.8
Tyre size FL				165/65 R 15 81 T
Tyre size FR				165/65 R 15 81 T
Tyre size RL				165/65 R 15 81 T
Tyre size RR				165/65 R 15 81 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Tyre RR, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Wheel cover FR, Missing, Replace



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Bodywork, Glue residues, Remove lettering



Historique Maintenance

Immatriculation: **FN-828-FA** Date de 1ère immatriculation: **23/01/2020**

Modèle: **Renault TWINGO Zen SCe 75 (TRANSFO) VF [5P] 5-75CH-4cv (bi-corps VU)**

Date	Kilométrage	Fournisseur	Descriptif
07/04/2026	194.562	GUEUDET ALLIANCE OISE COMPIEGNE	REVISION ET CLIM ET AIR ET BOUGIES
	0		LAMPE CODE AVD RPLT
	0		LAMPE RPLT
	0		BALAI ESSUIE GLACE AV AR
	0		BALAI ESSUIE GLACE AV AR
	0		DISQUES PLAQUETTES AV RPLT
	0		LIQUIDE DE FREIN
23/01/2026	191.498	FLEET SOLUTIONS FRANCE	LAMPE RPLT
19/01/2026	190.709	CENTRE DE CONTROLE TECHNIQUE 60	CONTROLE TECHNIQUE
17/03/2025	166.366	GUEUDET ALLIANCE OISE	PLAQUETTES AV RPLT
	0		RECYCLAGE
	0		PILE DE CLE RPLT
	0		REVISION ET CLIM
29/04/2024	136.702	GUEUDET ALLIANCE OISE	REVISION ET CLIM ET AIR ET BOUGIES
	0		COURROIE ACCESSOIRES RPLT
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		RECHARGE CLIM
	0		RECYCLAGE
15/05/2023	104.396	GUEUDET ALLIANCE OISE	REVISION ET CLIM
	0		BATTERIE RPLT
	0		PLAQUETTES AV RPLT
	0		AMORTISSEURS AV RPLT
	0		BALAI ESSUIE GLACE AR
	0		BALAI ESSUIE GLACE AV
	0		LAMPE RPLT
	0		LIQUIDE DE FREIN
13/06/2022	72.023	GUEUDET ALLIANCE OISE	AMORTISSEURS AR RPLT
	0		DISQUES PLAQUETTES AV RPLT
	0		RECYCLAGE
	0		BALAI ESSUIE GLACE AR
	0		REVISION
16/06/2021	50.697	SOC EXPLOIT GARAGE OISE	BALAI ESSUIE GLACE AV

Historique Maintenance

Immatriculation: **FN-828-FA**

Date de 1ère immatriculation: **23/01/2020**

Modèle: **Renault TWINGO Zen SCe 75 (TRANSFO) VF [5P] 5-75CH-4cv (bi-corps VU)**

Date	Kilométrage	Fournisseur	Descriptif
	0		PLAQUETTES AV RPLT
	0		RECYCLAGE
	0		REVISION ET CLIM ET AIR ET CARBURANT