



### Peugeot 2008: L940NT

Vinnnumber:	<b>VR3UKZKXZMJ625119</b>	Versionname:	<b>e-2008 100kW/ 50kWh Blue Lease Allure</b>
First Registrationsdate:	<b>3/07/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>100383</b>	Power Kw:	<b>100</b>
Bodytype:		Body colour:	<b>Gris Artense metaallak</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>737</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

### Options

Number of keys total	<b>2</b>	Lining semi-leather
GPS		Rear parking sensors
Autom climate control		
Radio multimedia		

### Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 96 / V / Aluminium	5,0 mm	Continental	Summer
	Right	215 / 60 / 17 / 96 / V / Aluminium	5,5 mm	Continental	Summer
Rear	Left	215 / 60 / 17 / 96 / V / Aluminium	6,2 mm	Continental	Summer
	Right	215 / 60 / 17 / 96 / V / Aluminium	6,0 mm	Continental	Summer

### Assistance equipment

Number of charging cables (rapid charge)	<b>1</b>
--	----------

### Interior, Stain, Cleaning



### Roof liner, Dent(s), Replace



### Door FL, Scratch(es), Repair and paint (complete)





Wing FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace and paint



Wheel arch cover RL, Scratch(es), Replace



Windscreen, Stone chip(s), Windscreen repair



Bumper F, Stone chip(s), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Paintless dent repair



Wheel arch cover FR, Scratch(es), Replace



Bumper moulding R, Scratch(es), Replace and paint



Bumper R, Scratch(es), Smart repair



<b>Kenteken</b>	L940NT
<b>Merk Model</b>	Peugeot e-2008 100kW/ 50kWh Blue Lease Allure
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	03-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
01-05-26	99.118	Remklauw(en) achterzijde
13-03-26	96.414	Reparatie band(en)
19-12-25	92.655	Reparatie band(en)
01-07-25	86.386	APK
07-03-25	80.872	Onderhoudsbeurt
07-03-25	80.872	Ruitenwischerblad(en) voorzijde
01-07-24	62.505	Sleutelbatterij
02-11-23	53.005	Airco reinigen
02-11-23	53.005	Onderhoudsbeurt
02-11-23	53.005	Remvloeistof
26-09-22	27.933	Airco reinigen
26-09-22	27.933	Onderhoudsbeurt
07-02-22	13.504	Onderhoudsbeurt
20-07-21	0	Accu