



Expertise

Protocol number: 46902434
Order No. / Reference: 26726622
Inspection date: 3 Aug 2026

Manufacturer: Volkswagen

Model: Passat Variant 2.0 TDI SCR DSG Business

VIN: WVGZZCJ8RD019696



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Passat Variant 2.0 TDI SCR DSG Business	
Vehicle Identification number	WVGZZCJ8RD019696
Mileage (Read)	179,865 km
First registration	5 Jun 2024
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	oyster silver-metallic (M7P)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	6,000 km
Last service on / at	03/2026 at 157,799 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB090927
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CTH 00001		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,250 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 95V	Summer tyres on Light alloy	Bridgestone	6mm / 6mm
2)	215/60 R16 95V	Summer tyres on Light alloy	Bridgestone	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 99H	Winter tyres on Steel	Dunlop	6mm / 6mm
2)	215/60 R16 99H	Winter tyres on Steel	Dunlop	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R18 99M	Summer tyres on Steel	Sonstige	3 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Turning brake function and evasive steering support
- Airbag for driver and front passenger (with front passenger airbag deactivation, including driver's side knee airbag)
- Ambient lighting
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- Exterior mirror housings in body color
- Hill start assist
- Vehicle tool kit
- Car2X
- Ceramique headliner
- decorative inlays
- Digital Cockpit Pro, multicolor (various info profiles selectable)
- Electronic differential lock XDS
- Electronic stability program and electromechanical brake booster
- Windscreen made of laminated safety glass, heat-insulating
- Luggage compartment floor adjustable to 2 heights
- Transmission: 7-speed DSG (7-speed dual-clutch transmission DSG)
- Rear spoiler in car color
- Interior mirror automatically dimming
- Child lock
- Air conditioning "Air Care Climatronic" (with active combination filter, rear controls and 3-zone temperature control)
- Intersection assistant
- Stainless steel loading sill protector
- LED taillights
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- Mesh partition
- Emergency call service (no registration required, service is activated upon delivery)
- Upholstery: Microfleece "ArtVelours Eco" (center panels of the front seats and outer rear seats)
- Rain sensor
- Wheels: Light alloy (4) "Venezia" 7J x 16, surface polished (tires 215/60 R 16, optimized for rolling resistance)
- Keyless start system without SAFE locking
- Rear side windows and rear window tinted
- Seats: ergoActive front seats, height-adjustable, with sliding thigh support
- Seats: Front seats with massage function
- Lane Assist and Traffic Jam Assist
- Lane change assistant "Side Assist", parking assistant and exit warning
- "Comfort" telephone interface with inductive charging function (charging power up to 15 W)
- Illuminated door handle recesses
- Front USB-C ports (2) (2 USB-C charging ports on the rear center console; charging power up to 45 W)
- Electronic immobilizer
- Distraction and fatigue detection
- Airbags: Front and rear head airbags, front side airbags, center airbag
- Anti-lock braking system (ABS)
- Adaptive Cruise Control (ACC) "Stop&Go"
- Folding and heated exterior mirrors, auto-dimming on the driver's side (with ambient lighting and passenger-side mirror lowering)
- third brake light
- Chrome trim on the side windows
- Roof rails, silver anodized
- Diesel particulate filter and SCR catalyst
- Tachometer
- Entry/warning lights in LED technology in the front doors
- Electronic parking brake including auto-hold function
- Electric windows, front and rear
- High beam assistant "Light Assist"
- Pedestrian detection
- Extendable and removable luggage compartment cover
- Speed limiter with predictive control
- Rear window heated
- rear window wiper
- Infotainment system with 32 cm (12.9 inch) display
- ISOFIX mounting points (for child seats on the outer rear seats and on the front passenger seat, i-Size compatible)
- Rear headrests (3)
- Front headrests (safety-optimized, longitudinally and height-adjustable)
- Paint finish: Pure White Uni
- LED lights in the front footwell, selectable light color
- LED headlights
- Headlight range control
- Navigation system
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Parking assistant "Park Assist" including parking aid
- Proactive occupant protection system
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system (passive)
- Rear View reversing camera
- Rear seat backrest asymmetrically split and foldable (with pass-through option)
- Electromechanical power steering (speed-dependent control)
- Seats: Comfort seats in the front
- Sun visors with illuminated makeup mirrors on driver and passenger side
- Start-stop system (with brake energy recuperation)
- Bumpers in body color, air intake with chrome trim, radiator grille with chrome trim
- Textile floor mats front and rear
- Ambient lighting with logo projection



- First aid kit, warning triangle and high-visibility vest
- Traffic sign recognition
- Central locking with remote control

Extra equipment

- Trunk tray index
- Navigation system "Discover Pro Max" in conjunction with "Business Premium" package (Head-up display - Infotainment system with 38 cm (15 inch) display (You can intuitively and conveniently select songs, system settings or vehicle data via touch or voice control) - Navigation system - IDA voice assistant and electronic voice amplification (Start the function with "Hello IDA" and turn the vehicle into an intelligent conversation partner))
- Package: Interior package in conjunction with Business Premium package (sport comfort seats in front - sliding rear center armrest with cup holders and storage compartment - seat center panels of the front seats and outer rear seats in microfleece "ArtVerlours Eco" - front seats with massage programs and active climate control - heated front seats - LED entry/warning lights in all doors - ambient lighting)
- Paint finish: Metallic
- Package: Acoustic package (Enhanced interior noise reduction - laminated safety glass, noise-reducing for side windows; rear and rear side windows tinted)
- Package: Business Premium Package (230V socket in the luggage compartment - Adaptive chassis control DCC Pro incl. driving profile selection - Luggage net - Luggage compartment floor adjustable to 2 heights - Head-up display - Multifunction steering wheel in leather, heated, with shift paddles - Progressive steering - Windscreen washer nozzles automatically heated at the front - Heated front seats)
- Package: Winter package including heated front seats (multifunction leather steering wheel, heated, with paddle shifters - front windscreen washer nozzles automatically heated)
- Wheels: Spare wheel, weight and space saving (on-board tools and jack)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - rear right side	Door - dent(s) - Smart repair
2	Door - front right side	Door - dent(s) - Smart repair
3	Steering system	Steering wheel - Scratch(es) - Smart repair
4	Rear bumper	Rear bumper - Scratch(es) - Smart repair
5	Roof	Roof - dent(s) - Smart repair
6	Bonnet	Insulation lining - Damaged - Replace
7	Vehicle glazing	Windscreen - Broken / torn - Replace



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Winterradsatz ist nicht Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.




Damage 1: Door - rear right side: Door - dent(s) - Smart repair



Damage 1: Door - rear right side: Door - dent(s) - Smart repair




Damage 2: Door - front right side: Door - dent(s) - Smart repair



Damage 2: Door - front right side: Door - dent(s) - Smart repair



Damage 3: Steering system: Steering wheel - Scratch(es) - Smart repair



Damage 3: Steering system: Steering wheel - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 5: Roof: Roof - dent(s) - Smart repair



Damage 5: Roof: Roof - dent(s) - Smart repair



Damage 6: Bonnet: Insulation lining - Damaged - Replace



Damage 7: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 7: Vehicle glazing: Windscreen - Broken / torn - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVVZZZCJ8RD019696

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Passat Variant 2.0 TDI SCR DSG
Business

Datum	KM-Stand	Beschreibung
26.03.2026	157.799	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
23.10.2025	122.292	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Getriebeöl ern/prüfen; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
07.04.2025	74.569	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
08.11.2024	41.114	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges