



BMW 5 Reeks (MKL): 2FQW914

Vinnumber:	WBY31FK090CT02507	Versionname:	i5 Berline (G60) eDrive40 340pk/cv 4p
First Registrationdate:	17/07/2024	Fiscalpower:	
Expertise Mileage:	43023	Power Kw:	69
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	3	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

245/45/19/102 Y				
Summer tyres:	Fr.L.	Hankook: 6 mm	Fr.R.	Hankook: 6 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				245/45 R 19 102 Y
Tyre size FR				245/45 R 19 102 Y
Tyre size RL				245/45 R 19 102 Y
Tyre size RR				245/45 R 19 102 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Interior, Damaged, Acceptable



Bumper F, Scratch(es), Repair and paint (complete)





Alloy rim FL, Scratch(es), Repair and paint (complete)



Alloy rim RL, Scratch(es), Acceptable



Charging cable (normal), Missing, Check



Bumper R, Scratch(es), Acceptable




Tyre RR, Deformed / Strained, Replace



Alloy rim RR, Scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Kenteken	2FQW914
Merk Model	BMW i5 Berline (G60) eDrive40 81,2kWh 340pk/cv 4p
Brandstofsoort	Elektrisch
Datum deel1	7/17/24

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/7/26	41,399	batterij	Vervangen
7/7/26	41,399	BMW/MINI service standaard omvang	Uitvoeren
7/7/26	41,399	BMW/MINI service voertuig-check	Uitvoeren
7/7/26	41,399	klein materiaal	
7/7/26	41,399	remvloeistof	Vervangen
7/7/26	41,399	ruitwisserrubber vooraan	Vervangen
7/7/26	41,399	service microfilter	Uitvoeren