



Peugeot 308 (UKL): 2CEN631

Vinnumber:	VR3FRHNPLNY566923	Versionname:	308 SW Active Pack 1.2 PureTech S&S 110pk/cv 5p
First Registrationdate:	24/06/2022	Fiscalpower:	
Expertise Mileage:	46134	Power Kw:	81
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	18800.0		
Maintenance	11 maand		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Type of Maintenance book	Digital maintenance	Type of Tow bar	No Tow bar
Type of GPS storage	N.A.		

Tyres

205/55/16/91 V				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Centre console, Scratch(es), Acceptable



Headrest RL, Missing, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Acceptable



Internal boot lining L, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Luggage compartment cover, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Bad repair, Repair and paint (complete)



Step R, Dent(s), Acceptable



Wheel cover FR, Scratch(es), Acceptable




Door FR, Dent(s) and scratch(es), Acceptable



Mirror side repeater R, Scratch(es), Acceptable



Outside rear-view mirror base R, Scratch(es), Acceptable



Outer door handle FR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable





Roof, Dent(s), Acceptable



Bodywork, Not original part, Check



Kenteken	2CEN631
Merk Model	Peugeot 308 SW Active Pack 1.2 PureTech S&S 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	6/24/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/5/26	44,000	45000 km	Uitvoeren
5/5/26	44,000	bougie	Vervangen
5/5/26	44,000	luchtfilter	Vervangen
5/5/26	44,000	luchtfilter interieur	Vervangen
5/5/26	44,000	nazicht technische keuring	Uitvoeren
5/5/26	44,000	oliezeef	Vervangen
5/5/26	44,000	remvloeistof	Vervangen
6/30/25	32,367	onderhoud 3e jaar	Uitvoeren
7/8/24	21,620	luchtfilter interieur	Vervangen
7/8/24	21,620	oliezeef	Vervangen
7/8/24	21,620	onderhoud 2e jaar	Uitvoeren
6/23/23	8,661	oliezeef	Vervangen
6/23/23	8,661	onderhoud 12 maand	Uitvoeren