

2-FWF-887


2-FWF-887 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FWF-887	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	JTNADADBXM0J019896
Model	Corolla	Cylinder Capacity	1.798 ^{cm³}
Model Versions	Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT /	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	16-09-2024
Color	Grey	Odometer	57.292 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Black
KW	103	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Rear Left	7 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Front Right	3 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Rear Right	7 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	None					

Damages

Acceptable



Damage Part

Hood

Damage Type

Dislocated / Loose

Repair Type

Repair

Acceptable

No



Damage Part

Reardoor – Right

Damage Type


Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Frontdoor – Right

Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Fender – Front Right

Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Windscreen – Front

Damage Type

Chipped

Repair Type

Window Repair

Acceptable

No



Damage Part

Frontdoor – Left

Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part
Reardoor – Left



Damage Type
Small scratch(es)

Repair Type
Acceptable

Acceptable
Yes



Damage Part
spoiler RB



Damage Type
Small dent(s)

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Trunkshelf



Damage Type
Missing

Repair Type
Replace

Acceptable
No