



BMW X3: K049JG

Vinnumber:	WBATS110309F07370	Versionname:	X3 xDrive 30eA 215kW
First Registrationdate:	9/02/2021	Fiscalpower:	
Expertise Mileage:	120611	Power Kw:	135
Bodytype:		Body colour	Saphirschwarz Metallic lak
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	846
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining leather
GPS		Rear parking sensors
Autom climate control		Hook
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 104 / H / Aluminium	5,0 mm	Pirelli	All season
	Right	225 / 60 / 18 / 104 / H / Aluminium	4,5 mm	Pirelli	All season
Rear	Left	225 / 60 / 18 / 104 / H / Aluminium	5,2 mm	Pirelli	All season
	Right	225 / 60 / 18 / 104 / H / Aluminium	5,0 mm	Pirelli	All season

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Interior, Dirty, Chemical cleaning



Wheel arch cover FL, Scratch(es), Replace



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Shutter / cover R, Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Reflector, Scratch(es), Replace



Rear light R, Scratch(es), Polish



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Rear spoiler, Scratch(es), Repair and paint (complete)



Bumper RM, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Kenteken	K049JG
Merk Model	BMW X3 xDrive 30eA 215kW
Brandstofsoort	Benzine
Datum deel1	09-02-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
17-11-25	107.568	Olie service
17-11-25	107.568	Remvloeistof
17-11-25	107.568	Reparatie band(en)
17-11-25	107.568	Sleutelbatterij
17-11-25	107.568	Voertuig diagnose
05-02-25	85.881	APK
05-02-25	85.881	Vervanging band
22-04-24	67.504	Bougie
22-04-24	67.504	Luchtfilter
22-04-24	67.504	Olie service
22-04-24	67.504	Onderhoudsbeurt
22-04-24	67.504	Ruitenwischerblad(en) voorzijde
27-09-22	33.139	Olie service
27-09-22	33.139	Sleutelbatterij
27-09-22	33.139	Vervanging band