MACADAM







Peugeot 308 (UKL): 2AVX847

Vinnumber:	**VF3LCYHZJMS152814**	Versionname:	**308 SW Business 1.5BlueHDi S&S 130pk/cv 5p**
First Registrationdate:	**11/08/2021**	Fiscalpower:	
Expertise Mileage:	**91018**	Power Kw:	**96**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**19400.0**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/16/91 H**			
	Fr.L.	**Michelin: 3 mm**	Fr.R.	**Michelin: 3 mm**
	Re.L.	**Nexen: 6 mm**	Re.R.	**Nexen: 6 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**205/55 R 16 91 H**
Tyre size FR	**205/55 R 16 91 H**
Tyre size RL	**205/55 R 16 91 V**
Tyre size RR	**205/55 R 16 91 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**1957072**
Tyre make RR	**1957072**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Bonnet, Stone chip(s), Acceptable





Door RL, Dent(s), Acceptable






Door FL, Dent(s), Acceptable




Wing RL, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable




Alloy rim RR, Scratch(es), Repair and paint (complete)





Wing RR, Dent(s), Acceptable




Door RR, Dent(s), Acceptable




Door FR, Dent(s), Acceptable




Outer sill R, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable




MACADAM

Onderhoudshistorie van: VF3LCYHZJMS152814

ALPHABET

Kenteken	2AVX847
Merk Model	Peugeot 308 SW Business 1.5BlueHDi S&S 130pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	8/11/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/27/26	87,472	90000 km	Uitvoeren
7/27/26	87,472	oliezeef	Vervangen
2/16/26	74,903	AdBlue injector	Vervangen
2/16/26	74,903	diagnose	Uitvoeren
2/16/26	74,903	kleine testrit	Uitvoeren
2/16/26	74,903	regeneratie partikelfilter/DPF	Uitvoeren
2/16/26	74,903	spiegel	Vervangen
7/9/25	65,528	remvloeistof	Vervangen
7/9/25	65,528	ruitenwisserrubber vooraan	Vervangen
5/15/25	63,724	remblokken vooraan	Vervangen
12/11/24	59,467	halogeenlamp	Vervangen
8/5/24	52,985	50000 km	Uitvoeren
8/5/24	52,985	oliezeef	Vervangen
3/25/24	46,929	halogeenlamp	Vervangen
7/20/23	35,625	34000 km	Uitvoeren
7/20/23	35,625	luchtfilter interieur	Vervangen
7/20/23	35,625	oliezeef	Vervangen
7/20/23	35,625	remvloeistof	Vervangen
6/24/22	15,996	15000 km	Uitvoeren
6/24/22	15,996	oliezeef	Vervangen