MACADAM








BMW 3 Reeks (KKL): 2ECH166

Vinnumber:	**WBA41FY010FR69032**	Versionname:	**320e Touring (G21) 2.0i 204pk/cv 5p Aut.**
First Registrationdate:	**28/08/2023**	Fiscalpower:	
Expertise Mileage:	**159488**	Power Kw:	**120**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**3**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/50/17/98 Y**			
	Fr.L.	**Bridgestone: 2 mm**	Fr.R.	**Bridgestone: 2 mm**
	Re.L.	**Bridgestone: 2 mm**	Re.R.	**Bridgestone: 2 mm**

Tyre profile depth FL	**2.0**
Tyre profile depth FR	**2.0**
Tyre profile depth RL	**2.0**
Tyre profile depth RR	**2.0**
Tyre size FL	**225/50 R 17 98 Y**
Tyre size FR	**225/50 R 17 98 Y**
Tyre size RL	**225/50 R 17 98 Y**
Tyre size RR	**225/50 R 17 98 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**1**

Bumper F, Scratch(es), Spot repair




Charging cable (normal), Missing, Check



Compressor, Missing, Check



Tyre repair kit, Missing, Check



Outside rear-view mirror R, complete, Scratch(es), Acceptable




Door FR, Scratch(es), Acceptable




Bodywork, Paint measurement, Acceptable



Onderhoudshistorie van: WBA41FY010FR69032

ALPHABET

Kenteken	2ECH166
Merk Model	BMW 320e Touring (G21) 2.0i 204pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	8/28/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/29/26	135,154	BMW/MINI service standaard omvang	Uitvoeren
4/29/26	135,154	BMW/MINI service voertuig-check	Uitvoeren
4/29/26	135,154	bougie	Vervangen
4/29/26	135,154	klein materiaal	
4/29/26	135,154	koelwatervloeistof	Bijvullen/-laden
4/29/26	135,154	remvloeistof	Vervangen
4/29/26	135,154	ruitenwisserrubber achter	Vervangen
4/29/26	135,154	ruitenwisserrubber vooraan	Vervangen
4/29/26	135,154	ruitenwisservloeistof	Bijvullen/-laden
4/29/26	135,154	service luchtfilter	Uitvoeren
4/29/26	135,154	service microfilter	Uitvoeren
4/29/26	135,154	service motorolie	Uitvoeren
8/26/25	101,759	BMW/MINI service standaard omvang	Uitvoeren
8/26/25	101,759	klein materiaal	
8/26/25	101,759	ruitenwisservloeistof	Bijvullen/-laden
8/26/25	101,759	service microfilter	Uitvoeren
8/26/25	101,759	service motorolie	Uitvoeren
12/30/24	67,376	BMW/MINI service standaard omvang	Uitvoeren
12/30/24	67,376	BMW/MINI service voertuig-check	Uitvoeren
12/30/24	67,376	bougie	Vervangen
12/30/24	67,376	klein materiaal	
12/30/24	67,376	service luchtfilter	Uitvoeren
12/30/24	67,376	service microfilter	Uitvoeren
12/30/24	67,376	service motorolie	Uitvoeren
4/26/24	35,226	BMW/MINI service standaard omvang	Uitvoeren
4/26/24	35,226	BMW/MINI voertuigcontrole	Uitvoeren
4/26/24	35,226	klein materiaal	
4/26/24	35,226	service microfilter	Uitvoeren
4/26/24	35,226	service motorolie	Uitvoeren