


2-FDW-148

2-FDW-148 · MY23 Mild-Hybrid 158 XTronic 2WD Business Premium · 6 August 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FDW-148	Fuel Type	Hybrid Gasoline
Manufacturer	NISSAN	VIN	SJNTAAJ12U1330399
Model	Qashqai	Cylinder Capacity	1.332 ^{cm3}
Model Versions	MY23 Mild-Hybrid 158 XTronic 2WD Business Premium	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	05-04-2024
Body Type	5 door hatchback	Odometer	78.817 ^{Km}
Color	Black	Numer Of Keys	2
Paint Type	Metallic	Interior	Darkgrey
Production Year	2024	Number Headrests	5
KW	116		

Images





Accessories

ABS	Electric windows front
Airbags	Electrically adjustable driver's seat
Alloy wheels	Leather steering wheel
ASR	Navigation system
Audio System	Panorama roof
Automatic air conditioning	Parking sensors
Bluetooth car kit	Rear view camera
Central door locking	Roller cover / parcel shelf
Centre armrest	Seat heating
Electric rear windows	Steering wheel multifunction
Electric sliding roof	

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 06-01-2026

Last maintenance odometer 65.693

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 ^{mm}	Bridgestone	235 ^{mm}	55 ^{mm}	18 ^{inch}	Summer
Rear Left	3 ^{mm}	Bridgestone	235 ^{mm}	55 ^{mm}	18 ^{inch}	Summer
Front Right	1 ^{mm}	Bridgestone	235 ^{mm}	55 ^{mm}	18 ^{inch}	Summer
Rear Right	3 ^{mm}	Bridgestone	235 ^{mm}	55 ^{mm}	18 ^{inch}	Summer
Spare Tire Type	Compressor					

Damages



Damage Part

Fender – Rear Right

Damage Type

Small scratch(es)

Repair Type

Touch-up /
Polish

Acceptable

No



Damage Part

Reardoor – Right

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Frontdoor – Right

Damage Type

Door-edge chipped

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Frontdoor - Right

Damage Type

Small scratch(es)

Notes

stootlijst

Repair Type

Plastic Repair

Acceptable

No



Damage Part

Frontdoor - Left

Damage Type

Door-edge chipped

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Fender - Rear Left

Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No