



SKODA SUPERB COMBI

|                                     |                   |                         |                                                                         |
|-------------------------------------|-------------------|-------------------------|-------------------------------------------------------------------------|
| Vinnumber:                          | TMBJH7NP0M7052396 | Versionname:            | SKODA SUPERB COMBI 2.0 CRTDI 110kW DSG7 Ambition 150PK 5d/p AUT(3V534D) |
| First Registrationdate:             | 23/03/2021        | Fiscalpower:            |                                                                         |
| Expertise Mileage:                  | 161703            | Power Kw:               | 110                                                                     |
| Bodytype:                           |                   | Body colour:            | Black                                                                   |
| Gearbox:                            | Automatic         | Type of rims (mounted): | Aluminium                                                               |
| Transmission:                       |                   | Parking lot:            | 3510                                                                    |
| Fueltype:                           | Diesel            |                         |                                                                         |
| Maintenance:                        | OK                |                         |                                                                         |
| Maintenance:                        | in 7900 km        |                         |                                                                         |
| Type of rims (mounted):             | Aluminium         |                         |                                                                         |
| Certificate of Conformity:          | Yes               |                         |                                                                         |
| Category:                           | Passenger Car     |                         |                                                                         |
| Registration Certificate Car (BE):  | Yes               |                         |                                                                         |
| Registration Certificate Home (BE): | No                |                         |                                                                         |

Options

|                                |                       |                       |                     |
|--------------------------------|-----------------------|-----------------------|---------------------|
| Number of keys total:          | 2                     | Seats electric F L    |                     |
| Cruise Control                 |                       | Luggage cover         |                     |
| Steering wheel multifunctional |                       | Front parking sensors |                     |
| Seats F heated                 |                       | Rear parking sensors  |                     |
| Radio multimedia               |                       | Type of Tow bar       | Tow bar collapsible |
| Type of headlighting           | Headlighting LED      |                       |                     |
| Type of GPS                    | GPS big screen color  |                       |                     |
| Type of Lining                 | Lining fabrics        |                       |                     |
| Type of climate control        | Autom climate control |                       |                     |
| Type of GPS storage            | HD                    |                       |                     |

Limited Technical Inspection

Tyres

|                       |       |                  |       |                  |
|-----------------------|-------|------------------|-------|------------------|
| 215/60/16/99 H        |       |                  |       |                  |
| Winter tyres:         | Fr.L. | Vredestein: 5 mm | Fr.R. | Vredestein: 5 mm |
|                       | Re.L. | Vredestein: 5 mm | Re.R. | Firestone: 5 mm  |
| Tyre profile depth FL |       |                  |       | 5.0              |
| Tyre profile depth FR |       |                  |       | 5.0              |
| Tyre profile depth RL |       |                  |       | 5.0              |
| Tyre profile depth RR |       |                  |       | 5.0              |
| Tyre size FL          |       |                  |       | 215/60 R 16 99 H |
| Tyre size FR          |       |                  |       | 215/60 R 16 99 H |
| Tyre size RL          |       |                  |       | 215/60 R 16 99 H |
| Tyre size RR          |       |                  |       | 215/60 R 16 99 H |
| Tyre type FL          |       |                  |       | Winter           |
| Tyre type FR          |       |                  |       | Winter           |
| Tyre type RL          |       |                  |       | Winter           |
| Tyre type RR          |       |                  |       | Winter           |
| Tyre make FL          |       |                  |       | 2480             |
| Tyre make FR          |       |                  |       | 2480             |
| Tyre make RL          |       |                  |       | 2480             |
| Tyre make RR          |       |                  |       | 2580             |

Assistance equipment

|                                          |     |            |     |
|------------------------------------------|-----|------------|-----|
| Repair kit                               | Yes | Compressor | Yes |
| Number of charging cables (normal)       | 0   |            |     |
| Number of charging cables (rapid charge) | 0   |            |     |

|                                 |         |
|---------------------------------|---------|
| Total cost ex VAT               | 1748,07 |
| Seat cover FL, Worn, Acceptable | 0,00    |



Backrest cover FL, Worn, Acceptable

0,00



Floor covering FL, Burned, Smart repair

116,69



Door panel RR, Scratch(es), Acceptable

0,00



Gear shift lever knob, Worn, Acceptable

0,00



Bonnet, Dent(s), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Engine insulation, Tear, Replace

57,96



Bumper grille, Broken, Replace

143,87



Outer door handle FL, Scratch(es), Acceptable

0,00



|                                  |      |
|----------------------------------|------|
| Door RL, Scratch(es), Acceptable | 0,00 |
|----------------------------------|------|



|                                              |      |
|----------------------------------------------|------|
| Wing RL, Dent(s) and scratch(es), Acceptable | 0,00 |
|----------------------------------------------|------|




|                                       |      |
|---------------------------------------|------|
| Alloy rim RL, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|



|                                         |       |
|-----------------------------------------|-------|
| Wing RL, Dent(s), Paintless dent repair | 95,47 |
|-----------------------------------------|-------|



|                                              |      |
|----------------------------------------------|------|
| Boot lid covering R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------------|------|



|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|



|                                          |      |
|------------------------------------------|------|
| Tailgate / Boot, Scratch(es), Acceptable | 0,00 |
|------------------------------------------|------|



|                             |      |
|-----------------------------|------|
| Step R, Dent(s), Acceptable | 0,00 |
|-----------------------------|------|



|                                                     |        |
|-----------------------------------------------------|--------|
| Roof pillar R, Dent(s), Repair and paint (complete) | 369,98 |
|-----------------------------------------------------|--------|



|                                         |       |
|-----------------------------------------|-------|
| Wing FR, Dent(s), Paintless dent repair | 95,47 |
|-----------------------------------------|-------|



|                                  |      |
|----------------------------------|------|
| Wing RR, Scratch(es), Acceptable | 0,00 |
|----------------------------------|------|



|                                  |      |
|----------------------------------|------|
| Door RR, Scratch(es), Acceptable | 0,00 |
|----------------------------------|------|



|                                              |      |
|----------------------------------------------|------|
| Door RR, Dent(s) and scratch(es), Acceptable | 0,00 |
|----------------------------------------------|------|



|                                  |      |
|----------------------------------|------|
| Door FR, Scratch(es), Acceptable | 0,00 |
|----------------------------------|------|



|                                  |      |
|----------------------------------|------|
| Wing FR, Scratch(es), Acceptable | 0,00 |
|----------------------------------|------|



|                                                       |        |
|-------------------------------------------------------|--------|
| Roof, Chemical pollution, Repair and paint (complete) | 868,63 |
|-------------------------------------------------------|--------|

