



CITROËN BERLINGO: FD-874-QB

Vinnumber:	VF77DBHW6JN543049	Versionname:	CITROËN BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)
First Registrationdate:	5/02/2019	Fiscalpower:	
Expertise Mileage:	174086	Power Kw:	55
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total:	2	Tow bar:	
Number keys remote:	1	Radio:	
Windows electric F:		Rear parking sensors:	
Cruise Control:		Sliding door right-side:	
Type of climate control:	Manual climate control	Seat cover lining:	Lining Other

Tyres

195/70/15/104 S				
Summer tyres:	Fr.L.	Falken: 0%	Fr.R.	Falken: 0%
	Re.L.	Michelin: 0%	Re.R.	Michelin: 15%
Tyre profile depth FL				8.7
Tyre profile depth FR				8.8
Tyre profile depth RL				8.0
Tyre profile depth RR				7.1
Tyre size FL				195/70 R 15 104 S
Tyre size FR				195/70 R 15 104 S
Tyre size RL				195/70 R 15 104 S
Tyre size RR				195/70 R 15 104 S
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				1957074
Tyre make FR				1957074
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror base L, Broken, Replace



Door FL, Scratch(es), Paint



Side panel L, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Deformed / Strained, Replace



Bumper moulding FR, Scratch(es), Replace



Wing FR, Scratch(es), Paint



Outside rear-view mirror housing R, Scratch(es), Replace



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Boot door lining L, Broken, Replace



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Deformed / Strained, Repair and paint (complete)



Rear light L, Broken, Replace



Bodywork, Glue residues, Remove lettering



Historique Maintenance

Immatriculation: **FD-874-QB** Date de 1ère immatriculation: **05/02/2019**

Modèle: **Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
05/01/2026	165.452	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
30/09/2025	159.750	CLARA AUTOMOBILES	INJECTEUR ADBLUE RPLT
	0		DISQUES PLAQUETTES AR RPLT
	0		LAMPE CODE AVD RPLT
17/06/2025	156.796	CLARIS AUTOMOBILES	DIVERS ECHAPPEMENT
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
	0		REVISION
30/01/2025	145.934	CLARIS AUTOMOBILES	ESSAI
	0		KIT ACCESSOIRES RPLT
	0		POMPE A EAU RPLT
	0		KIT DISTRIBUTION RPLT
	0		DIAG
25/07/2024	131.172	CLARIS AUTOMOBILES	REVISION ET CLIM ET AIR ET CARBURANT
	0		LAMPE AR RPLT
	0		LAMPE RPLT
	0		BALAIS ESSUIE GLACE AV
06/03/2024	119.998	SARL CD AUTOMOBILES	LIQUIDE DE REFROIDISSEMENT RPLT
	0		PLAQUETTES AR RPLT
	0		PLAQUETTES AV RPLT
	0		REVISION ET CLIM
18/01/2024	113.985	SARL CD AUTOMOBILES	ESSAI
	0		RESERVOIR ADBLUE RPLT
22/12/2023	111.796	CLARIS AUTOMOBILES	LAMPE RPLT
	0		LAMPE AR RPLT
13/12/2023	102.409	CLARIS AUTOMOBILES	FAP RPLT
19/06/2023	94.709	CLARIS AUTOMOBILES	LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM ET AIR
06/03/2023	86.449	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
22/11/2022	81.531	GARAGE MAUBLANC	LAMPE CODE AVD RPLT
14/11/2022	78.125	GARAGE MAUBLANC	BATTERIE RPLT

Historique Maintenance

Immatriculation: **FD-874-QB**

Date de 1ère immatriculation: **05/02/2019**

Modèle: **Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
20/05/2022	75.902	GARAGE MAUBLANC	DIVERS CLIM
	0		DISQUES PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
	0		FILTRE CLIM RPLT
	0		REVISION
	0		REVISION
28/10/2021	59.408	GARAGE MAUBLANC	LAMPE CODE AVD RPLT
05/07/2021	50.909	GARAGE MAUBLANC	RECYCLAGE
	0		ADBLUE
	0		BALAIS ESSUIE GLACE AV
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE A AIR RPLT
	0		REVISION
04/01/2021	44.055	GARAGE MAUBLANC	BATTERIE RPLT
08/06/2020	33.651	GARAGE MAUBLANC	REVISION
	0		RECYCLAGE
	0		FILTRE CLIM RPLT