




Audi A3:

Vinnumber:	WAUZZZGY5PA022400	Versionname:	
First Registrationdate:	16/09/2022	Fiscalpower:	
Expertise Mileage:	103184	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3813
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

205/55/16/91 W				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 91 W
Tyre size FR				205/55 R 16 91 W
Tyre size RL				205/55 R 16 91 W
Tyre size RR				205/55 R 16 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Total cost ex VAT	1009,52
Bumper spoiler F, Scratch(es), Spot repair	148,33



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Wing FL, Scratch(es), Acceptable	0,00
----------------------------------	------




Outside rear-view mirror base L, Scratch(es), Acceptable	0,00
--	------



Outside rear-view mirror housing L, Scratch(es), Acceptable	0,00
---	------



Outer door handle FL, Scratch(es), Acceptable	0,00
---	------



Alloy rim RL, Scratch(es), Repair and paint (complete)	133,03
--	--------




Wing RL, Dent(s) and scratch(es), Repair and paint (complete)	431,58
---	--------



Charging cable (normal), Missing, Check	0,00
---	------



Bumper R, Scratch(es), Repair and paint (complete)	296,58
--	--------



Outside rear-view mirror R, complete, Scratch(es), Acceptable	0,00
---	------

