

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number			Code / Agency				Date accident 22/06/2026								
				Expert code			Adjuster code			Policy number			Injured person can recover the VAT NOT ESTABLISHED								
Date assignment 22/06/2026		Date first survey 03/07/2026		Place Ascoli Piceno		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate ALPHABET ITALIA FLEET MANAGEMENT SPA - VIA LUNELLI 27 TRENTO (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) PEUGEOT 308 SW Business BlueHDi 130 EAT8 S&S								Plate GD416TC		Vin Chassis VF3LCYHZKLS235470				First Registration 26/11/2020							
Usage status NON CONOSCIUTO		Km 116637		Tyres % 90		Color GRIGIO		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0		Wheelbase								Seats No. 0		Axles 0			
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations										SR		LA		VE		ME		D.M. S.C.		Costs of spare parts	
										Dif		Time		Dif		Time		Dif		Time	
1 9678566780		Internal stone guard of rear wheel arch						R		S		S		S							
1 96774433ZD		Internal lower cladding of central pillar						L		S		S		S							
1 Codice Ricambio		Copertura sup. ant. console centr.								S		S		S							
1 96778808XT		Front door external moulding						R		S		S		S							
1 98004069XT		Rear door external moulding						R		S		S		S							
1 1610102080		Front door						L		L		L		L							
1 9817303180		Front bonnet								L		L		M							
1 9800177780		Roof								L		M		M							
1 1610102180		Front door						R		L		L		M							
1 1623050980		rear mudguard						R		L		M		M							
1 Codice Ricambio		Cerchio ruota lega ant. - PRM						L													
1 Codice Ricambio		Ripr. cerchio ruota lega ant.						R													
1 Codice Ricambio		Ripr. cerchio ruota post.						R													
1 Codice Ricambio		Ripr. cerchio ruota post.						L													
1 Codice Ricambio		Retrovisore est. - PRM						L													
1 Codice Ricambio		Parafango ant. - PRM						L													
1 Codice Ricambio		Paraurti ant.																			
1 Codice Ricambio		Calotta retrovisore						R													
1 Codice Ricambio		Porta post. - PRM						R													
1 Codice Ricambio		Paraurti post. + s/r accessori																			
1 Codice Ricambio		Volante - USURA																			
1 Codice Ricambio		Pannello int. portello post. - PRM																			
1 Codice Ricambio		Ossatura vano porta post. - PRM						L													
1 Codice Ricambio		Copertura post. console centr. - PRM																			

New for old value (N)	Remarks
	Pneum. Barum 205/55 R16. Vhl sporco, grandinato.