

## » Overview

**Order number:** 1002409134  
**Order completed:** 16.04.2026 12:20  
**Report number:** 10455111  
**VIN:** TMBGR7NW5N3075955



Front Left 3/4



Rear Right 3/4



Mileage

## » Vehicle Data

<b>Vehicle category:</b>	Passenger Car
<b>Vehicle type:</b>	SUV
<b>Make:</b>	Skoda
<b>Model:</b>	Kamiq
<b>Manufacturers and type code:</b>	8004 / AVS
<b>Date of first registration:</b>	28.03.2022
<b>Mileage:</b>	20,705 km
<b>Proof of mileage:</b>	ReadOff
<b>Exterior colour:</b>	Moon-Weiss Metallic
<b>Roof colour:</b>	Moon-Weiss Metallic
<b>Propulsion:</b>	Front
<b>Fuel:</b>	Petrol
<b>Engine size (cc):</b>	1,000 ccm
<b>Performance:</b>	81 kW (111 PS)
<b>Length:</b>	
<b>Height:</b>	
<b>Width:</b>	
<b>Permitted total weight:</b>	
<b>Wheelbase:</b>	
<b>Number of powered axles:</b>	2
<b>Cylinders:</b>	3
<b>Euronorm:</b>	Euro 6
<b>Number of doors:</b>	4
<b>Number of seats:</b>	5
<b>Gearbox:</b>	Manual 6-speed
<b>Upholstery type:</b>	Lining fabrics
<b>Interior colour:</b>	Satin schwarz/grau Formhimmel
<b>Number of keys:</b>	2

## » Documents & Maintenance

<b>Statutory inspection date:</b>	04.2027
<b>Registration certificate available:</b>	Yes
<b>Registration certificate received:</b>	Yes
<b>License plate:</b>	None
<b>Maintenance book:</b>	Digital
<b>Maintenance:</b>	Not testable
<b>Maintenance last date:</b>	
<b>Maintenance last mileage:</b>	
<b>Remainder until next maintenance:</b>	365 Day(s)

"FRONT ASSIST" - radar scan of the space in front of the car, incl. City ANB, without "ADAPTIVE CRUISE ASSISTANT"

2 USB Typ-C vorne

3-cylinder SI engine 1.0 l unit 05C.A

3-cylinder SI engine 1.0 l/81 kW TSI base engine is TJ4/TC5

3-point seat belt for center rear seat

3-point seat belts in front, with tensioner and height adjustment

3-point seat belts, outer rear with ECE label

4 doors

6-speed manual transmission

8 speakers (passive)

Activated carbon canister (Evaporative Emission Control System (EVAP))

Additional exterior noise suppression

Additional front underbody guard

Additional interior noise suppression

Alloy wheels 6.5J x 17

Alternator 140 A

AM TOUR DE

Ambient lightning white

Ambition

Antenna for FM reception only, diversity

Antifreeze up to -25 degree Celsius tolerance up to -30 degree C

Axial and vertical adjustable steering column

Basic LED rear lights

Battery 320 A (49 Ah)

Black Piano

Black roof rails

Bluetooth

Boardcomputer Maxidot

Body-colored bumpers

Breakaway interior rearview mirror, auto-dimming

Breakdown kit

Care connect 1 year

Carrier frequency 433.92 MHz-434.42 MHz

Center armrest in front "Jumbo Box"

Center console

Central locking w/ radio remote control, interior controls, without SAFELOCK

Child seat anchors f. child seat system i-Size, 2x top tether and child seat anchors in front on front passenger side

Climatronic with impact pressure control, CFC-free

Crossover

Curb weight range 1

DAB - Digital radio reception

Decorative inserts

Disc brakes in front (Geomet D)

Disc brakes in rear (Geomet D)

Door panels with upholstery

Driver knee airbag

Driving on the right

Electronic cruise control + Speedlimiter

Electronic immobilizer

Electronic stability control (ESC)

Emblems

Emergency call system eCall+

Emission standard EU6 AP

Equipment options subset for Germany

Extended and proactive pedestrian and cyclist protection

Exterior mirrors, power-adjustable/ heated

Floor mats, front and rear

Fresh air intake system with combination filter

Front stabilizer bar

Front-wheel drive

Fuel system for fuel-injected SI engine (tropicalized)

Gearshift knob/handle in leather

Glove compartment door with light

Grey ceiling

Headlight range control

Heated washer nozzles in front

Heat-reflecting windshield

Height-adjustable head restraints for front seats

Hill start assist

Initial standard fuel filling

Installation differentiation for transmission MQ 200\_GA -- vehicle components --

Instrument cluster, km/h speedometer

Interior bars and air vents frame Chrome

Key for locking system with remote control

Labels in German, French and Dutch

LED headlamps with cornering light

Left exterior mirror, convex

Left-hand drive

LongLife Service Regime

Luggage compartment cover

Luggage net	Standard climatic zones
Manual height adjustment for front seats	Standard decorative trims
Manual in German	Standard manufacturing sequence
Manually adjustable lumbar support in front seats	Standard paint coating
MirrorLink	Standard pedal cluster
Mounting fixture in luggage compartment	Standard rear axle
Multi-function steering wheel	Standard Seats
Nameplate set in basic style	Standard tailgate
No special purpose vehicle, standard equipment	Standard version
Non-smoker's package	Standard wheel bolts
Not hot country	Start-stop system with regenerative braking
Operating permit, alteration	Sun visors with mirror and airbag label on front passenger side
Outside door mirrors and door handles in body color	Sunset
Part set, complying with vehicle type for Germany, various parts	Suspension range 24 installation control only, no requirement forecast
Plane luggage/load compartment floor in rear	Tailgate without electrical opening
Power steering	Three rear head restraints
Power windows with comfort operation and circuit breaker	Tire pressure monitoring system
Radiator grille	Tires 205/55 R17 91V Low Rolling Resistance
Radio Bolero 8"	Tires without specification of tire brand
Rear and front parking sensors	Tool kit
Rear axle weight, type 1	Transport protection film (minimum protection) with additional transport protection measures
Rear floor panel module, type 1	Trims for alloy wheels
Rear overhang, short	Type approval country Germany
Rear shock absorption	Unsplit rear seat bench, split folding backrest
Rear window wiper and washer system with intermittent control	Variant
Refrigerant R1234yf	Vehicle class differentiation -655-
Regional code " ECE " for radio	Visual and acoustic seat belt reminder, electric contact
Remote Access / Pro-active service	Warranty prolongation for 5 years, until 50 000 km
Right exterior mirror, convex	Weight range 13 installation control only, no requirement forecast
Scuff plates in door apertures	Wheelbase
Seat heater for front seats separately controlled	Windshield wiper intermittent control with light/rain sensor
Seat trim covers in fabric	With multifunction camera
Semiconductors	With trim panel
Separate daytime running light with automatic headlight control and manual Coming and Leaving Home feature	With umbrella
Service indicator 30 000 km or 2 years ( variable )	Without "drive select"
Shock absorption in front	Without adapter
Side airbag in front with curtain airbag	Without additional malfunction display
Single-tone horn	Without additional side body covers (stone guard)
Special identification label for EC for M1 passenger vehicles	Without alternative drive system
Special model 2022	Without auxiliary heater/parking heater
Spectacle storage compartment/bracket	Without backrest release for front seats
Spurhalte assist	Without bracket

Without camera systems/accident sensors  
Without delivery equipment  
Without drawers under front seats  
Without driver alert system  
Without dynamic road sign display  
Without ECO function  
Without electronic steering column lock  
Without extended safety system  
Without fire extinguisher  
Without folding table on front seat backrest  
Without front fog lamps  
Without headlamp washer system  
Without heat accumulator/auxiliary heater  
Without lane change assist  
Without light control  
Without navigation device  
Without partition  
Without protective side molding  
Without refrigerator/glove compartment cooling system  
Without roof insert (standard roof)  
Without second battery  
Without socket  
Without trailer hitch  
Without two-sided floor surface  
Without voice control  
Without washer fluid level indicator  
Without waste bin

## » Tyres

### MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Continental	Front	Left	Summer	Aluminium	205/55 R 17 91 V	6.0 mm
Continental	Front	Right	Summer	Aluminium	205/55 R 17 91 V	6.0 mm
Continental	Rear	Left	Summer	Aluminium	205/55 R 17 91 V	6.0 mm
Continental	Rear	Right	Summer	Aluminium	205/55 R 17 91 V	6.0 mm

**Permitted:** Yes

**Roadworthy:** Yes

### SPARE/EMERGENCY TYRE & ACCESSORIES

**Repair kit present:** Yes

**Repair kit expiration date:** 12.2025

**Compressor present:** Yes

## » Devaluation Factors

Nr	Location	Damage type	Repair type
1	Alloy rim FR polished	Scratch(es)	Visual depreciation
2	Engine insulation	Tear	Replace
3	Bumper spoiler F	Scratch(es)	Smart repair
4	Door FR	Scratch(es)	Smart repair
5	Outside rear-view mirror housing R	Scratch(es)	Smart repair
6	Tyre repair kit	Expired	Replace

## » Usage Damages

Nr	Location	Damage type	Repair type
1	Rear spoiler	Scratch(es)	Acceptable
2	Boot lid covering R	Scratch(es)	Acceptable

## » Commercial devaluation

<b>Known previous damages:</b>	No
<b>Previous damages detectable:</b>	No
<b>Repainting present:</b>	No
<b>Paint thickness measurement performed:</b>	Yes - no abnormalities/deviations

### PAINTTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

## » Notes On The Assessment

**Details of the assignment and the scope of the assessment:**

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

**Vehicle identification:**

TMBGR7NW5N3075955

VIN checked and matches documentation

**Vehicle condition:**

Average general condition

**Inspection condition:**

Restricted

**Lifting platform/lifting equipment used:**

Yes

**Testdrive carried out:**

Yes

**Engine test carried out:**

Yes

» **Remarks**

This copy was generated electronically. It is valid without an original signature.

## » Commercial Pictures



Front Left 3/4




Front Right 3/4




Rear Left 3/4




Rear Right 3/4



Mileage



Sill outer L



Sill outer R



Chassis nr



Wheel FL



Wheel FR




Wheel RL




Wheel RR



Central console




Engine compartment




Documents




Interior arrangement




Registration Certificate



History Maintenance



Interior - front




Interior - rear



Tirefit expiration date



Underbody scan



GPS/Radio

## » Devaluation Damages

### DEVALUATION FACTORS

1 - Alloy rim FR polished - Scratch(es) - Visual depreciation



2 - Engine insulation - Tear - Replace



3 - Bumper spoiler F - Scratch(es) - Smart repair




4 - Door FR - Scratch(es) - Smart repair



5 - Outside rear-view mirror housing R - Scratch(es) - Smart repair




6 - Tyre repair kit - Expired - Replace



## USAGE DAMAGES

1 - Rear spoiler - Scratch(es) - Acceptable



2 - Boot lid covering R - Scratch(es) - Acceptable

