MACADAM









SKODA OCTAVIA COMBI: GS-452-RL

Vinnumber:	**TMBJJ8NX7RY068011**	Versionname:	**SKODA OCTAVIA COMBI 2.0 TDI 150 DSG7 Ambition VP [5P] bva 7-150CH-8cv (break)**
First Registrationdate:	**28/11/2023**	Fiscalpower:	
Expertise Mileage:	**185516**	Power Kw:	**110**
Bodytype:	**Break**	Body colour	**Blue**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Grey**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Tow bar	
Number keys remote	**2**	Radio	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Front parking sensors	
Steering wheel leather		Rear parking sensors	
Type of climate control	**Autom climate control**	Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**205/60/16/92 H**			
	Fr.L.	**Hankook: 10%**	Fr.R.	**Hankook: 10%**
	Re.L.	**Hankook: 10%**	Re.R.	**Hankook: 10%**

Tyre profile depth FL	**7.4**
Tyre profile depth FR	**7.4**
Tyre profile depth RL	**7.5**
Tyre profile depth RR	**7.5**
Tyre size FL	**205/60 R 16 92 H**
Tyre size FR	**205/60 R 16 92 H**
Tyre size RL	**205/60 R 16 92 H**
Tyre size RR	**205/60 R 16 92 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Side repeater L, Crack, Replace




Windscreen, Stone chip(s), Windscreen repair




Bumper F, Scratch(es), Paint




Door RR, Dent(s) and scratch(es), Acceptable





Tailgate / Boot, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable




ALPHABET

Historique Maintenance

Immatriculation: **GS-452-RL** Date de 1ère immatriculation: **28/11/2023**

Modèle: **Skoda OCTAVIA COMBI 2.0 TDI 150 DSG7 Ambition VP [5P] bva 7-150CH-8cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
13/08/2026	179.030	INTENZ POITIERS	Entretien - Standard
			Entretien - Standard
			Filtre à air (Remplacement)
			Petite Fourniture moteur
			Pièce principale de moteur
			Filtre à Carburant
			Filtre à Air
			Filtre d'habitacle (Remplacement)
			Filtre à carburant (Remplacement)
			Plaquettes - Avant (Remplacement)
			Petite Fourniture moteur
			Frein, élément de Friction
			Roulement (Remplacement)
			Frein, élément de Friction
			Plaquettes - Arrière (Remplacement)
			Frein, élément de Friction
			Frein, élément de Friction
			Roulement (Remplacement)
			Diagnostic électronique (Contrôle)
			REVISION ET CLIM ET AIR ET CARBURANT
			PLAQUETTES AV RPLT
			PLAQUETTES AR RPLT
			REVISION
			Diagnostic électronique (Contrôle)
			Filtre à Pollen
			Pieces
			Petite Fourniture moteur
02/04/2026	157.162	INTENZ POITIERS	BOITIER SERVITUDE INTELLIGENT BSI RPLT
10/03/2026	152.953	INTENZ POITOU BY AUTOSPHERE	ADBLUE
			REVISION
			RECYCLAGE
09/10/2025	123.517	INTENZ POITOU BY AUTOSPHERE	BALAIS ESSUIE GLACE AV

Historique Maintenance

Immatriculation: **GS-452-RL** Date de 1ère immatriculation: **28/11/2023**

Modèle: **Skoda OCTAVIA COMBI 2.0 TDI 150 DSG7 Ambition VP [5P] bva 7-150CH-8cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
			DISQUES PLAQUETTES AR RPLT
			ADBLUE
			REVISION ET CLIM
			RECYCLAGE
			DISQUES PLAQUETTES AV RPLT
13/05/2025	93.514	INTENZ POITOU BY AUTOSPHERE	REVISION
			ADBLUE
02/01/2025	66.095	INTENZ POITOU BY AUTOSPHERE	PLAQUETTES AR RPLT
			REVISION ET CLIM
			PLAQUETTES AV RPLT
18/07/2024	31.543	INTENZ POITOU BY AUTOSPHERE	REVISION
			BALAIS ESSUIE GLACE AV
			RECYCLAGE