



Ford Focus: G119KH

Vinnumber:	WF0PXXGCHPKJ38374	Versionname:	Focus 2.0 EcoBlue 110kW ST-Line Business wagon
First Registrationdate:	17/10/2019	Fiscalpower:	
Expertise Mileage:	171737	Power Kw:	110
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Diesel	Parking lot	582
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Rear parking sensors
GPS		
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 40 / 18 / 95 / Y / Aluminium	5,8 mm	Bridgestone	Summer
	Right	235 / 40 / 18 / 95 / Y / Aluminium	5,6 mm	Bridgestone	Summer
Rear	Left	235 / 40 / 18 / 95 / Y / Aluminium	5,8 mm	Bridgestone	Summer
	Right	235 / 40 / 18 / 95 / Y / Aluminium	6,1 mm	Bridgestone	Summer

Assistance equipment

Interior, Dirty, Cleaning



Service, Maintenance, Execute



Wing RL, Scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Stone chip(s), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Wing FR, Scratch(es), Repair and paint (complete)



Outer door handle RR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Bumper RM, Scratch(es), Repair and paint (complete)



Kenteken	G119KH
Merk Model	Ford Focus 2.0 EcoBlue 110kW ST-Line Business wagon
Brandstofsoort	Diesel
Datum deel1	17-10-19

Datum reparatie	Kilometerstand	Reparatie omschrijving
16-10-25	154.307	APK
16-10-25	154.307	Fijnstofmeting
16-10-25	154.307	Vervanging band
21-07-25	0	Accu
02-06-25	143.816	Onderhoudsbeurt
02-06-25	143.816	Remblokken voorzijde
02-06-25	143.816	Ruitenwisserblad(en) voorzijde
18-10-24	125.728	APK
18-10-24	125.728	Fijnstofmeting
13-06-24	114.803	Onderhoudsbeurt
13-06-24	114.803	Remvloeistof
08-01-24	99.676	Vervanging band
02-01-24	99.099	Reparatie band(en)
27-12-23	98.629	Ruitenwisserblad(en) voorzijde
20-12-23	98.013	Reparatie band(en)
06-10-23	91.713	APK
06-10-23	91.713	Fijnstofmeting
21-06-23	85.851	Onderhoudsbeurt
21-06-23	85.851	Ruitenwisserblad(en) voorzijde
05-04-23	81.177	Vervanging band
08-12-22	72.501	Sleutelbatterij
12-10-22	70.790	APK
09-06-22	61.786	Motorolie verversen
09-06-22	61.786	Onderhoudsbeurt
09-06-22	61.786	Vervanging band
27-08-21	41.783	Vervanging band
22-03-21	31.836	Onderhoudsbeurt
05-11-19	1.486	Band(en)