



Peugeot 308 (UKL): 2CEH223

Vinnumber:	VR3FCYHZTNY559027	Versionname:	308 SW Allure 1.5BlueHDi S&S 130pk/cv 5p EAT8
First Registrationdate:	23/06/2022	Fiscalpower:	
Expertise Mileage:	118812	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenance book present		
Type of GPS storage	HD		

Tyres

	225/45/17/94 W			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Fulda: 7 mm	Re.R.	Fulda: 7 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				225/45 R 17 94 W
Tyre size FR				225/45 R 17 94 W
Tyre size RL				225/45 R 17 94 Y
Tyre size RR				225/45 R 17 94 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				2484
Tyre make RR				2484

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

MOT certificate, Missing, Replace



Engine insulation, Tear, Replace



Bonnet, Dent(s), Acceptable



Bumper F, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Acceptable



Step L, Dent(s), Acceptable




Door RL, Dent(s), Paintless dent repair



Wing RL, Dent(s) and scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Outer sill R, Scratch(es), Acceptable



Kenteken	2CEH223
Merk Model	Peugeot 308 SW Allure 1.5BlueHDi S&S 130pk/cv 5p EAT8
Brandstofsoort	Diesel
Datum deel1	6/23/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/10/25	107,445	klein materiaal	
12/10/25	107,445	remblokken vooraan	Vervangen
3/4/25	79,166	onderhoud 3e jaar	Uitvoeren
3/4/25	79,166	ruitenwisserrubber achter	Vervangen
3/4/25	79,166	ruitenwisserrubber vooraan	Vervangen
5/16/24	47,001	50000 km	Uitvoeren
5/16/24	47,001	luchtfILTER interieur	Vervangen
5/16/24	47,001	oliezeef	Vervangen
5/16/24	47,001	remvloeistof	Vervangen
7/5/23	25,531	klein materiaal	N.v.t.
7/5/23	25,531	onderhoud 1e jaar	Uitvoeren