MACADAM








BMW X1 (UKL): 2CGX348

Vinnumber:	**WBA71AC0805V55971**	Versionname:	**X1 (F48) 18d sDrive 2.0d 136pk/cv 5p**
First Registrationdate:	**22/07/2022**	Fiscalpower:	
Expertise Mileage:	**55144**	Power Kw:	**100**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**6000.0**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/55/17/97 W**			
	Fr.L.	**Continental: 5 mm**	Fr.R.	**Continental: 5 mm**
	Re.L.	**Continental: 6 mm**	Re.R.	**Continental: 6 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**225/55 R 17 97 W**
Tyre size FR	**225/55 R 17 97 W**
Tyre size RL	**225/55 R 17 97 W**
Tyre size RR	**225/55 R 17 97 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Bumper F, Scratch(es), Repair and paint (complete)












Bumper moulding F, Scratch(es), Smart repair




Alloy rim FL, Scratch(es), Repair and paint (complete)




Mirror side repeater L, Waterinfiltration, Acceptable




Wing RR, Dent(s), Paintless dent repair




Door RR, Dent(s), Paintless dent repair






Door RR, Scratch(es), Acceptable




Wing trim FR, Scratch(es), Acceptable




Door FR, Dent(s), Acceptable




Outside rear-view mirror base R, Scratch(es), Acceptable




Bodywork, Paint measurement, Acceptable



Onderhoudshistorie van: WBA71AC0805V55971

ALPHABET

Kenteken	2CGX348
Merk Model	BMW X1 (F48) 18d sDrive 2.0d 136pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	7/22/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/11/25	41,516	BMW/MINI service standaard omvang	Uitvoeren
12/11/25	41,516	BMW/MINI voertuigcontrole	Uitvoeren
12/11/25	41,516	service brandstoffilter	Uitvoeren
12/11/25	41,516	service microfilter	Uitvoeren
12/11/25	41,516	service motorolie	Uitvoeren
6/18/25	35,324	BMW/MINI service standaard omvang	Uitvoeren
6/18/25	35,324	controle niveaus	Uitvoeren
6/18/25	35,324	remvloeistof	Vervangen
10/28/24	26,713	BMW/MINI service standaard omvang	Uitvoeren
10/28/24	26,713	BMW/MINI service voertuig-check	Uitvoeren
10/28/24	26,713	remblokken achter	Vervangen
10/28/24	26,713	ruitenwisserrubber achter	Vervangen
10/28/24	26,713	ruitenwisserrubber vooraan	Vervangen
10/28/24	26,713	service luchtfilter	Uitvoeren
10/28/24	26,713	service microfilter	Uitvoeren
10/28/24	26,713	service motorolie	Uitvoeren
10/5/23	13,463	BMW/MINI service standaard omvang	Uitvoeren
10/5/23	13,463	BMW/MINI voertuigcontrole	Uitvoeren
10/5/23	13,463	service microfilter	Uitvoeren
10/5/23	13,463	service motorolie	Uitvoeren