

INSPECTION REPORT


End of contract

GENERAL INFO

File	315741
License plate	2CBP771
Vehicle identification number	WMW21B50903P39765
Dossier	2021230058
Make	Mini Mini Count.Coo.S E ALL4 2
Mileage	43871
First registration	23/05/2022
client availability date	18/06/2026
inspectionDate	23/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	N
237	Wing Front right / Trim / Replace	N
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
801	See External Expertise	N
12	Bumper Front // Smart Repair Large	N
54	Headlight / Front left / Replace	Y
124	Light / Rear left / Replace	Y
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	Y
213	Door Front Right // Painting	Y
244	Light / Front Right / Replace	Y
551	Central Console // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
641	Rear Right Door Interior Coating // Repair	N

Damage Pictures



Roof // Smart Repair Medium-dent




Headlight / Front left / Replace-scratch



Light / Front Right / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Central Console // Repair-scratch



Rear Right Door Interior Coating // Repair-scratch



Door Front Right // Painting-scratch



Rear Bonnet // Polish-scratch




Light / Rear left / Replace-scratch



Wing Front right / Trim / Replace-scratch



Front Bonnet // Polish-scratch



See External Expertise-dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent