



Vehicle History Report

2021 PORSCHE CAYENNE

Vehicle reference:

WP1ZZZ9YZMDA51014

Body type:

Estate

Gearbox

type:

Automatic

Engine size:

2995 cm³

Hybrid

vehicle:

Electric,
Petrol

Combustion

engine

power:

250 kW /

340 hp

Drive:

AWD

Quick check



Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.



Import

Not a private import

Legend



No issues reported or indicated



Valuable Information



Requires attention



Data unavailable

Damage overview


12/2024

Affected area (5):

Location reference, does not indicate the extent of the damage.

Reported in
Italy

Damage
type/cause
Not available



Damage severity:



Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

CARFAX tips



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.



Recommended maintenance

Default schedule

Provided by CARFAX Europe



Vehicle age

5 years, 3 months

Routine maintenance is essential for preserving a vehicle's reliability.



Critical past due service tasks

These service tasks are expected based on the vehicle age. Verify if they were completed.

Before buying, ask the seller:

- Are service records available?
- Were the following services performed?

Engine oil and oil filter **due 5 times**

Change every year

Brake fluid **due 2 times**

Change every 2 years



Costly upcoming service tasks

Before buying, confirm whether:

- Any of the upcoming maintenance tasks are already completed.
- You've accounted for related costs in your future budget.

Brake discs and pads

Inspect yearly, replace as needed

Tires

Inspect yearly, replace as needed



CARFAX tips



Keeping up with scheduled servicing is a strong indicator that the vehicle has been well cared for and is in good overall condition.

Owners

BETA



Owner(s) in Italy

Purchase year:	2021
Damage reported on:	12/2024

Technical details



Engine and performance

Hybrid vehicle

Electric, Petrol

Combustion engine power

250 kW / 340 hp

Electric engine power

Not available

Total system power

Not available



Environment and consumption

EU emission standard

Euro 6



Weight

Curb weight

2 435 kg

Max payload

620 kg

Gross vehicle weight

3 055 kg



Dimensions

Length

4 931 mm

Width

1 983 mm

Wheelbase

2 895 mm

 Other information

European vehicle category
M1

EU standard code
e13*2007/46*0900*11

Number of doors
5

Number of seats
5

History information

Date	Mileage	Event
2021-04-26		Registered in Italy
12/2024		Damage reported in Italy

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

CARFAX Glossary

Model year

This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions.](#)