
APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	
Make:	SKODA
Model / version:	OCTAVIA COMBI
Vin:	TMBJW7NX7NY013600
Plate:	
Mileage:	199081
SOH:	
First registration:	24/01/2022
Color:	Lava Blue me

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	3
Original key:	✓

PICTURES

































VIN INFORMATION

Radio	Radio avec système de navigation	4 haut-parleurs
Transmission séquentielle	6 rapports	5 portes
Break	Projecteurs antibrouillard	Lave-projecteurs
Feux arrière à LED	Buses de lave-vitre avant chauffantes	Essuie-lunette arrière
Equipement Style	Becquet arrière	Entourage de vitres chromé
Matière : alliage	Lettre repère (J)	Diamètre avant 18
Diamètre arrière 18	Largeur avant 7,5	Largeur arrière 7,5
Diamètre avant 18	Diamètre arrière 18	Hauteur avant 40
Hauteur arrière 40	Indice de vitesse avant Y	Indice de vitesse arrière Y
Largeur avant 225	Largeur arrière 225	Climatisation automatique 2 zones
Climatisation réfrigérant 1234YF	Accoudoir central avant	Accoudoir central arrière
Pare-soleil conducteur éclairé	Pare-soleil passager éclairé	Ordinateur de bord
Hybride essence	1395 cm3	1.40 litre
150 kw	204 ch	Métallisée vernissée
Maintenance standard	Freins arrière à disques	Frein à main électrique

Rétroviseur gauche chauffant	Rétroviseur droit chauffant	Rétroviseurs rabattables électriques
Rétroviseur intérieur jour/nuit automatique	Siège avant gauche chauffant	Sièges avant chauffants
Siège avant gauche réglable en hauteur	Sièges avant réglable en hauteur	3ème appui-tête arrière
Fixations Isofix siège passager avant	Fixations Isofix aux places arrières	Garnitures tissu
Suspension adaptative	Volant cuir	Volant multifonction
Aide au stationnement avant	Aide au stationnement arrière	Caméra avant
Caméra arrière de recul	Affichage lecture des panneaux de signalisation	Verrouillage centralisé à commande à distance
Carte mains libres	Appel de secours	Lunette arrière teintée foncée
Vitres portes arrière teintées foncées	Vitres de custode teintées foncées	Fixotoit aluminium
Airbag passager	Airbag passager désactivable	Airbag latéraux avant
Airbag de genoux	Airbag rideaux avant	Airbag rideaux arrière
Freinage d'urgence assistée autonome (urbain)	depuis 12.21	éclairage périphérique Ambiente
sièges ar réglables électrique	sécurité enfants électrique	capteur de luminosité/capteur de pluie
prise de courant 230 V	câble de charge pour prise domestique Mode 2 Type 2 E/F (10A)	radio avec récepteur numérique
train à quatre bras	système de gonflage des pneus	services Online
échappement Sound	réservoir à charbon actif (EVAP)	transmission hybride M-HEV
vide-poches dans le coffre		

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm	Semperit	225/45/R18/95V	Winter	Aluminium	✗
Front right	5 mm	Semperit	225/45/R18/95V	Winter	Aluminium	✗
Rear left	5 mm	Semperit	225/45/R18/95V	Winter	Aluminium	✗
Rear right	5 mm	Semperit	225/45/R18/95V	Winter	Aluminium	✗

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Interior	Dirty
2	Boot lid covering R	Scratch(es)
3	Bonnet	Dent(s) and scratch(es)
5	Bumper R	Dent(s) and scratch(es)
6	Alloy rim RR	Dent(s) and scratch(es)
7	Wing RR	Dent(s) and scratch(es)
9	Roof	Dent(s)
10	Alloy rim FR	Dent(s) and scratch(es)

Total: 8

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
4	Wing RL	Bad repair	✓	✗	✗
8	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 2

DAMAGES DETAILS

1 - Interior - Dirty







2 - Boot lid covering R - Scratch(es)









3 - Bonnet - Dent(s) and scratch(es)










5 - Bumper R - Dent(s) and scratch(es)






6 - Alloy rim RR - Dent(s) and scratch(es)





7 - Wing RR - Dent(s) and scratch(es)







9 - Roof - Dent(s)






10 - Alloy rim FR - Dent(s) and scratch(es)







4 - Wing RL - Bad repair - Renta®





8 - Bodywork - Dent(s) and scratch(es) - Renta®






SIGNATURE - IN A

DAMAGES